

DATE 0906Z 09 SEP 63

SECRET

ROUTING	
1	4
2	5
3	6

25 YEAR RE-REVIEW

TO DIRECTOR

25X1

FROM [redacted]

ACTION:

INFO : OSA 1-15

ROUTINE

IN 90462

TOR: 1156Z 09 SEP 63

25X1

25X1 TO [redacted] INFO

CITE [redacted] 0350

25X1

REF [redacted] 2600

25X1

TECH ANALYSIS OF [redacted] DUPE OF MISSION 6066

1. TRACK-1 RCVR B-SCAN APPEARS NORMAL EXCEPT FOR BEGINNING AND END OF MISSION. NUMEROUS INTERCEPTS AT BOTH THESE POINTS, SWEEP AND RETURN TIME APPEARED NORMAL ON SCOPE, BUT WAS SLIGHTLY AFFECTED BY SPURS.

TRACK-2 RCVR A-THIS RCVR HAD A FAILURE IN THAT THE MARKER PULSES PRODUCED WERE DISTORTED. NUMEROUS INTERCEPTS AT BEGINNING AND END OF MISSION. CAN UNDERSTAND ODINCH DIFFICULTY IN FREQ READOUT DUE TO DISTORTION OF MARKER PULSES.

TRACK-3 RCVVR C-SCAN APPEARS NORMAL, 3.5 MS SWEEP, 3.0 MS RETURN, ACTIVITY MUCH THE SAME AS TRACK-1.

2. THE SYSTEM FLOWN ON THIS MISSION (SER 5) SCHEDULED TO BE LOADED ON NEXT TRAINING FLIGHT. WILL CHECK TAPE AND NOTIFY HQS OF ANY DEVELOPMENTS.

END OF MESSAGE

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification